

# Cleaning & Maintenance

## ROUTINE CLEANING - ALL PRODUCTS

Use a non-abrasive damp cloth and mild detergent. Do not use granular material, bleach or acids.

## DAMAGE, WEAR AND TEAR

We use the best industry-standard materials but all surfaces are vulnerable to scratching. Powder-coat paint and lacquers show scratches more with dark colours than light colors.

## POWDER-COATED METAL

Surface scuff marks can be easily removed using Big Wipes. Chips and deep scratches can be painted over with external paint. Small pots of paint can be obtained from us.

## STAINLESS STEEL

The surface is protected by a hard, clear finish specially formulated to prevent finger-marks showing.

## BIRCH PLY - PLAIN AND TINTED

Scratches on plain ply tops do not tend to show. Scratches that show on dark tinted ply can be masked to some extent using tinted polishing wax.