




Connect charging dock to mains



Place Opac onto dock




4 LED lights will flash to indicate charging is taking place



Remove Opac when charged





Carry Opac to designated location




Place Opac into the recess on a device until you hear the click.

Connecting bases with linking kit









Please contact us for longer runs.